DAILY WORK ORDER	
Work Site: Bossert Manufacturing	Work Period: 7/14/87
Contractor: O. H. Materials Contractor Rep.: Paul Street	OSC: Jack D. Harmon
WORK PLANNED/AUTHORIZED:  1.) Initiate the removal of duct work in area #12  2.) Continue loading clean debris from area #13 and final sweep  3.) Set-up sample storage area. Initiate planning ground surface sampling  4.) Complete cleaning debris from area #16 & #1 pending dumpster delivery  5.) Load-out PCB dumpsters and manifest.  6.) Remove debris from areas #10, #11, & #7 staging in area #3 for disposal  7.) Continue removing steel sump debris with magnet	WORK ACCOMPLISHED FROM PREVIOUS WORK ORDER:  Yes No Continues  1.) (x) ( ) ( )  2.) ( ) ( ) (x)  3.) (x) ( ) ( )  4.) ( ) ( ) (x)  5.) (x) ( ) ( )  6.) ( ) (x)
EQUIPMENT PLANNED/AUTHORIZED: (3) Vans (2) Pick-up Truck (1) Decon trailer (3) Bobcats (1) Command Post Trailer (1) Crew Trailer (3) 12K Pools (1) Portable Eye Wash (1) Car (6) Radioes (1) 50K Pool (1) Water Treatment System  w/ appurtenances (2) High-Pressure Water Laser  w/hoses (1) Mini-Trackhoe (20) Propane tanks (1) Hi-Lift (1) 185 CFM Air Compressor (1) Cascade System (4) Porta-Johns (1) 955 Loader (1) 6-CY Dumpster (1) 3-in (3) Submersible Pumps: (2) 2-in (3) Satelites (3) Hilti-guns (2) 6.5KW Generators (1) Pneumatic Forklift	EQUIPMENT USED FROM PREVIOUS DAY:  All Authorized COMMENTS:
PERSONNEL AUTHORIZED: (1) Response Manager (2) Laborer (1) Lab Technician (2) (2) Lab Technician (1) (8) Clean-up Technician (1)	(1) Foreman (3) (2) Foreman (2) (1) Field Clerk (4) Clean-up Technician (2) (1) Operator (2)

Contractor Signature:	_OSC Signature:
Ph	
Date: 7/14/87	Pate: 7114/87